

Table of Contents

13 x13 Fixed Gantry Table

Overview	1
Cut Lumber	2
Drill X Chassis	3
Assemble X Chassis	6
Bushings	6
Rails	7
X Table	8
Install Bushings	10
Install Rails	11
X Leadnut Assembly	12
Install X Leadscrew	14
Gantry Overview	16
Gantry Bottom	17
Gantry Sides	17
Install Y Rails	19
Z Carriage Overview	20
Z Carriage Front	21
Z Carriage Back	22
Install Screws	22
Install Z Plate	23
Y Leadnut Assembly	24
Install Y Stepper	26
Template for Z Rails	27
Z Stepper Plate	27
Spindle Support	28
Tension Rods	29
Cross Tie	30
Install Z Rails	30
Install Z Stepper	31
Z Leadnut Assembly	31
Spindle Supports	33
Wire Protection	34
Axis Names	35
Switch X and Y Axis Names	35
Software Settings, Introduction	35
Steps per Revolution, Stepper	36
Micro-Stepping	36
Leadscrews	36
Starts and Turns per Inch	37
Determining Steps per Unit (Inch)	37
Resolution	37
Speed (Velocity) and Acceleration	38
Porter Cable 7301	39
Leadscrew to Stepper Coupler	39
Materials	41